FIG. 1




FIG.







FIG. 3










FIG. 5





FIG. 6






FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14





FIG. 15








FIG.17








FIG 19





FIG 20

				$\int 36$
REDUNDANCY GROUP	UNIT			
	1	2	3	4
A	Active	Spare	No	No
В	No	Active	Spare	No
C	№	No	Active	Spare
D	Spare	No	No	Active

FIG. 21



UNIT2					
A	В	D'			

UNIT 4

UNIT 3				
A'	С	B'		




FIG. 23

				5 30
REDUNDANCY GROUP	UNIT			
	1	2	3	4
A	No	Active	Spare	No
В	No	Active	Spare	No
С	No	No	Active	Spare
D	No	Spare	No	Active

FIG. 24

